

## **Contents**

Introduction..... 1  
G Code List..... 2  
M Code List..... 3  
Sample Part ..... 5  
Sample Program ..... 6  
Tool Layout .....25  
How To Take Tool Offsets .....26  
Notes on taking offsets: .....29

## **Introduction**

The Purpose of this document is to give additional information for the instructional videos. Please click on the Table of Content to jump to the desired information.



## G Code List

### ■ G CODE LIST

CODE	DESCRIPTION	CODE	DESCRIPTION
G00	Positioning (Rapid traverse)		
G01	Linear interpolation (Cutting feed)	G87	S1 deeping cycle(X axis)
G02	Circular interpolation CW	G88	S1 cross tapping(X axis)
G03	Circular interpolation CCW	G90	Outer diameter/internal diameter cutting cycle
G04	Dwell	G92	Thread cutting cycle(auto)
G12.1	Polar coordinate interpolation mode	G96	Constant round speed.
G13.1	Polar coordinate interpolation cancel mode	G97	Constant speed.
G17	Xp Yp plane selection	G98	Per minute feed ( mm/min )
G18	Zp Xp plane selection	G99	Per revolution feed ( mm/rpm )
G19	Yp Zp plane selection	G320	British Imperial System (Restart machine.)
G28	Return to reference position	G321	Metric System (Restart machine.)
G30	2nd reference position return	G300	Return to programme reference point
G32	Thread cutting	G800	Main spindle angle deflection settingof C axis
G40	Tool nose radius compensation cancel	G900	Main and sub spindle angle deflection setting
G41	Tool nose radius compensation right		
G42	Tool nose radius compensation left		
G50	Coordinate system setting		
	Max. spindle speed setting		
G70	Fine cutting cycle		
G71	Horizontal cutting repeated cycle		
G72	Vertical cutting repeated cycle		
G73	Forming Processing repeated cycle		
G74	End face grooving cycle		
	End face peck drilling cycle		
G75	Side grooving cycle		
	Side peck drilling cycle		
G76	Threading Canned Cycle		
G80	Cancel machining cycle		
G83	Cycle for Z axis deep face drilling		
G84	Cycle for Z axis face tapping		

5-9

## M Code List

■ M CODE LIST FOR MAIN SYSTEM


CODE	DESCRIPTION	CODE	DESCRIPTION
M00	Programme stop	M114	Side/ Face drilling CCW
M01	Optional programme stop	M115	Side/Face drilling stop
M02	End of program	M133	Main/Sub spindle synchronous CW
M03	Spindle CW	M134	Main/Sub spindle synchronous CCW
M04	Spindle CCW	M135	Main/Sub spindle synchronous stop
M05	Spindle stop	M142	Main/Sub Z axis synchronous running
M06	Spindle position start	M143	Main/Sub Z axis synchronous running cancel
M07	Spindle position cancel	M144	Main/Sub C axis synchronous running
M08	Coolant oil start	M145	Main/Sub C axis synchronous running cancel
M09	Coolant oil cancel	M191	Sub program for top cutting by new bar ( non guide bush mode )
M10	Spindle chuck close	M192	Sub program for top cutting by new bar ( guide bush mode )
M11	Spindle chuck open	M211	Start the first backup M code
M13	Spindle CW+ coolant oil	M212	cancel the first backup M code
M14	Spindle CCW+ coolant oil cancel	M213	Start the second backup M code
M30	End of program	M214	Cancel the second backup M code
M32	Cut off detection	M215	Start the third backup M code
M34	Threading 45° back-off	M216	Cancel the third backup M code
M35	Threading 90° back-off	M217	Start the forth backup M code
M38	C axis mode enable	M218	Cancel the forth backup M code
M39	C axis mode unable	M219	Start the fifth backup M code
M43	Cut-off tool turning head of bar automatically	M220	Cancel the fifth backup M code
M60	Bar feeder pressure off	M500	Spindle load detector
M61	Bar feeder pressure on	M660	
M62	bar feeder backward by bar change	M1000 M1100	Main/Sub system Waiting command
M63	Confirm bar change finished		
M94	Single block bypass mode OFF		
M95	Single block bypass mode ON		
M98	Call sub programmeme		
M99	Programmeme cycle/sub programmeme finish		
M100	Spindle position (M100 C___;)		
M110	Sub spindle chuck close		
M111	Sub spindle chuck open		
M113	Side/Face drilling CW		



■ M CODE LIST FOR SUB SPINDLE

CODE	DESCRIPTION	CODE	DESCRIPTION
M00	Programme stop	M211	Start the first backup M code(W/ \$1share)
M01	Optional programme stop	M212	Cancel the first backup M code (W/ \$1share)
M02	End of programme	M213	Start the second backup M code(W/ \$1share)
M03	Spindle CW	M214	Cancel the second backup M code (W/ \$1share)
M04	Spindle CCW	M215	Start the third backup M code(W/ \$1share)
M05	Spindle stop	M216	Cancel the third backup M code (W/ \$1share)
M06	Spindle position	M217	Start the forth backup M code(W/ \$1share)
M07	Spindle position cancel	M218	Cancel the forth backup M code (W/ \$1share)
M08	Coolant oil	M219	Start the fifth backup M codes(W/ \$1share)
M09	Coolant oil cancel	M220	Cancel the fifth backup M code (W/ \$1share)
M10	Spindle chuck close	M231	Start inner coolant oil for sub spindle
M11	Spindle chuck open	M232	Stop inner coolant oil for sub spindle
M13	Spindle CW+ coolant oil	M500   M660	Spindle load detector
M14	Spindle CCW+ coolant oil cancel		
M18	Parts conveyor active	M1000   M1100	Main/Sub system Waiting command
M24	Sub Spindle air blow on		
M25	Sub Spindle air blow off		
M30	End of programme		
M31	Pusher forward (Cylinder pusher)		
M32	Pusher backward (Pnumatic cylinder pusher)		
M33	Pnumatic cylinder pusher Enjecting parts detection		
M34	Threading 45° back-off		
M35	Threading 90° back-off		
M38	C axis mode enable		
M39	C axis mode unale		
M98	Call sub programmeme		
M99	Programmeme cycle/sub programmeme finish		
M100	Spindle position (M100 C ___;)		
M113	Face drilling CW		
M114	Face drilling CCW		
M115	Face drilling stop		

**Sample Part**



NO.	REV.	DATE	BY	CHKD.	APP.

## **Sample Program**

\$1  
(DEMO SL20Y2)  
(MAIN SPINDLE)  
(.6875 TITANIUM MATERIAL)

M43S1500F0.0005  
M11  
G4X1.0  
G300X-0.02Z3.75T0101  
G50Z0.  
M0  
M10  
G4X1.0  
M0  
G0X1.0Z-0.005  
M1000  
M1

N11(INsert DRILL .435)  
G97M13S1091T1111  
G99G0X0Y0Z-.1M9  
M9  
Z-.1  
M217  
G1Z.25F.001  
Z2.5F.0025  
G0Z-.1  
M218  
M5  
M1

N12(DRILL .325)  
G97M13S1468T1212  
G99G0X0Y0Z-.1  
Z-.1  
Z2.3  
G1Z2.45F.0025  
G0Z-.1

Z2.43

G1Z2.5

G0Z-.1

Z2.49

G1Z2.55

G0Z-.1

M5

M1

N13(BB R.015 ROUGH)

G97M13S800T1313

G99G0X.5265Y0Z-.1

Z-.1

G1Z-.005F.0035

G3X.4253Z.0456R.0506

G1Z2.4121

X.4

G0Z-.05

X.5265

G1Z-.0015

G3X.4323Z.0456R.0471

G1Z2.4135

X.4

G0Z-.005

G1X.69

G0Z-.1

M5

M1

N14(BB R.008 FINSH)

G97M13S750T1414

G99G0X.5113Y0Z-.2

Z-.1

Z-.02

G1Z0F.001

G3X.4353Z.038R.038

G1Z2.4097F.002

X.3397Z2.4575F.0005

X.3255Z2.4504

G0Z-.1

M5

M1

N2222(TURN R.016 ROUGH)

G97M13S1431T0202

G99G0X.690Y0Z-.01  
G1X-.035F.0025  
G0X.7Z-.02  
G1X.63F.005  
Z.477  
X.69  
G0Z-.0026  
G1X.63  
X.57  
Z-.0078  
X.63  
G0Z-.0026  
G1X.57  
X.5172  
Z-.0025  
X.5345  
G2X.5601Z.0028R.0181  
G1X.614Z.0298  
G2X.6246Z.0426R.0181  
G1Z.3987  
G2X.6186Z.4087R.0181  
G1X.57Z.4454  
Z.500  
G0X.69  
G0Z-.02  
M5  
M9  
M1

N3(TURN R.008 FINSH)  
G97M13S1600T0303  
G99G0X.71Y0Z-.1  
Z-.001  
G1X.4F.0025  
G0X.5497Z-.02  
G1Z-.0005F.005  
G2X.5617Z.002R.0085  
G1X.6156Z.0289  
G2X.6206Z.0349R.0085  
G1Z.3711  
G2X.6156Z.3771R.0085  
G1X.5637Z.403  
G0X.69  
Z-.01  
X.5497



G1Z0F.0025  
G2X.561Z.0023R.008  
G1X.6149Z.0293  
G2X.6196Z.0349R.008  
G1Z.3711  
G2X.6149Z.3767R.008  
G1X.5627Z.4028  
G0X.69  
Z0  
X.65  
G1X.3  
G0Z-.1  
M5  
M1

N5(EXTERNAL THREADING)

G97M13S1000T0505  
G99G0X.690Y0Z-.15  
G92X.6Z.44F.050  
X.595  
X.590  
X.585  
X.580  
X.575  
X.570  
X.565  
X.564  
X.564  
G0X.75  
Z-.1  
M5  
M1

(SECOND ROUGH)

N22(TURN R.016 ROUGH ROUGH SECOND TIME)

G97M13S1431T0202  
G99G0X.690Y0Z.3  
Z.4  
G1X.63F.005  
Z1.25  
X.69  
G0Z.4  
G1X.63  
X.57

Z1.25  
G0X.75  
M5  
M1

N33(TURN R.008 FINSH SECOND TIME)  
G97M13S1600T0202  
G99G0X.7Y0Z.3997  
X.69  
G1X.6946F.0025  
X.6239Z.3644  
X.55Z.4013  
Z1.25  
G0X.7  
Z1.25  
G0X.69  
Z.4  
M5  
M1

N222(.3125 END MILL )  
M38  
T2222  
M113S3=1100  
G98G0Y.75X.9Z.904C0.  
G1Y.482F5.  
X-.9  
Z.961  
X.9  
Z.903  
X-.9  
Z.962  
X.9  
G0Y.750  
M115  
M39  
M1

N23(.218 CARBIDE DRILL )  
M38  
T2323  
M113S3=1500  
G98G0Y.75X0Z.952C104.  
Y.6  
G1Y.25F1.0

Y.6F5.0  
G0Y.750  
M115  
M39  
M1

N22(TURN R.016 ROUGH THIRD TIME)  
G97M13S1431T0202  
G99G0X.690Y0Z1.2  
X.6  
G1Z1.560F.005  
G0X.69  
Z1.2  
G1X.57  
X.5677  
Z1.56  
X.57Z1.5603  
X.6  
Z1.85  
G0X.75  
M5  
M1

N33(TURN R.008 FINSH THIRD TIME)  
G97M13S1600T0202  
G99G0X.710Y0Z1.23  
G1X.55Z1.24F.0025  
Z1.562  
X.5563  
G2X.5843Z1.575R.013  
G1Z1.85  
G0X.73  
M5  
M1

(FOURTH ROUGH)

N222(TURN R.016 ROUGH FOURTH TIME)  
G97M13S1500T0202  
G99G0X.7Y0Z2.0  
X.6894  
G1Z2.7F.005  
G0X.75  
M5  
M1

N333(TURN R.008 FIN FOURTH TIME)

G97M13S1500T0303

G99G0X.710Y0Z2.0

X.6847

G1Z2.7F.0025

G0X.75

M5

M1

N4(GROOVE TOOL)

G97M13S1200T0404

G99G0X.690Y0Z1.8762

X.69

G1X.65F.0035

G0X.69

X.666

G1X.61

G0X.69

X.626

G1X.5957

G0X.69

Z1.8935

G1X.65

G0X.69

X.666

G1X.61

G0X.69

X.626

G1X.5957

G0X.69

Z1.9188

G1X.65

G0X.69

X.666

G1X.61

G0X.69

X.626

G1X.57

G0X.69

X.586

G1X.53

G0X.69

X.546

G1X.5177

G0X.69  
Z1.9442  
G1X.65  
G0X.69  
X.666  
G1X.61  
G0X.69  
X.626  
G1X.57  
G0X.69  
X.586  
G1X.53  
G0X.69  
X.546  
G1X.5177  
G0X.69  
Z1.9695  
G1X.65  
G0X.69  
X.666  
G1X.61  
G0X.69  
X.626  
G1X.57  
G0X.69  
X.586  
G1X.53  
G0X.69  
X.546  
G1X.5177  
G0X.69  
Z1.9948  
G1X.65  
G0X.69  
X.666  
G1X.61  
G0X.69  
X.626  
G1X.57  
G0X.69  
X.586  
G1X.53  
G0X.69  
X.546  
G1X.5177

G0X.69  
Z2.0202  
G1X.65  
G0X.69  
X.666  
G1X.61  
G0X.69  
X.626  
G1X.57  
G0X.69  
X.586  
G1X.53  
G0X.69  
X.546  
G1X.5177  
G0X.69  
Z2.0455  
G1X.65  
G0X.69  
X.666  
G1X.61  
G0X.69  
X.626  
G1X.57  
G0X.69  
X.586  
G1X.53  
G0X.69  
X.546  
G1X.5177  
G0X.69  
Z2.062  
G1X.6897  
G0X.69  
Z2.0827  
G1X.6897  
G0X.69  
Z2.1033  
G1X.6897  
G0X.69  
Z2.124  
G1X.6897  
G0X.69  
Z2.1477  
G1X.6897

G0X.69  
Z2.1713  
G1X.6897  
G0X.69  
Z2.195  
G1X.6897  
G0X.69  
Z2.2115  
G1X.65  
G0X.69  
X.666  
G1X.61  
G0X.69  
X.626  
G1X.5857  
G0X.69  
Z2.2175  
G1X.65  
G0X.69  
X.666  
G1X.61  
G0X.69  
X.626  
G1X.5857  
G0X.69  
Z2.234  
G1X.6897  
G0X.69  
( MAIN SPINDLE )  
Z1.882  
G1X.5907F.0015  
G2X.5727Z1.891R.009  
G1X.5149  
X.5138Z1.8911  
G3X.5127Z1.892R.001  
G1Z2.000  
G0X.7  
( MAIN SPINDLE )  
Z2.067  
G1X.6847  
G3X.6567Z2.053R.014  
G1X.5149  
X.5138Z2.0529  
G2X.5127Z2.052R.001  
G1Z1.99

G0X.69  
( MAIN SPINDLE )  
Z2.195  
G1X.6847  
G2X.6567Z2.209R.014  
G1X.5827  
G3X.5807Z2.21R.001  
G1Z2.211  
G0X.69  
( MAIN SPINDLE )  
Z2.239  
G1X.6847  
G3X.6567Z2.225R.014  
G1X.5827  
G2X.5807Z2.224R.001  
G1Z2.210  
G0X.71  
(BACK GROOVE)  
Z2.632  
G1X.481F.002  
G0X.71  
Z2.68  
G1X.481  
G0X.71  
Z2.686  
G1X.5619F.0015  
G3X.5596Z2.6832R.004  
G1X.5554Z2.6811  
G3X.5356Z2.677R.014  
G1X.4807  
Z2.65  
G0X.71  
Z2.615  
G1X.6847  
G2X.6567Z2.629R.014  
G1X.4807  
Z2.665  
G0X.75  
M5  
M1  
  
N25(.234 CARBIDE DRILL )  
M38  
T2525  
M113S3=1468



G98G0Y1.00X0Z1.930C90.

Y.72

G1Y.3F1.0

Y.7F5.0

G0H180.

G1Y.3F1.0

Y.7F5.0

G0Y1.0

M115

M39

M1

N24(.093 CARBIDE DRILL )

M38

T2424

M113S3=2600

G98G0Y1.00X0Z1.930C0.

Y.72

G1Y.3F1.0

Y.7F5.0

G0Y1.0

M115

M39

M1

N99(CUT OFF W.098)

G97M13S1000T0101

G99G0X0.710Z3.487

M1007

M133S1000R0

M1008

M1009

M8

G1X-0.05F0.001

M1010

M1011

M135

M9

M95

G4U0.1

G4U0.1

(/M192S1600F0.0016)

G4U0.1

M94

M1012

M5  
M30

\$2  
(DEMO SL20Y2)  
(SUB SIDE)  
G28W0.  
M1000

N1(TURN R.016)  
G97M14S1600T3131  
G99G0X0.72Y0  
Z.005  
G1X-.035F.0025  
G0X.63Z.05  
G1Z-.8345  
X.6535  
G3X.6897Z-.8526R.0181  
G1Z-.8676  
X.69  
G0Z.0026  
G1X.63  
X.57  
Z-.8345  
X.63  
G0Z.0026  
G1X.57  
X.51  
Z-.0093  
X.5577Z-.0331  
G3X.5683Z-.046R.0181  
G1Z-.8345  
X.57  
G0Z.0026  
G1X.51  
X.45  
Z.0025  
X.4714  
G3X.497Z-.0028R.0181  
G1X.51Z-.0093  
G0Z.0026  
G1X.45  
X.39  
Z.0025  
X.45

G0Z.0026

G1X.39

X.3768

Z.0025

X.39

G0X.69

Z.1

M5

G28W0

M1

N36(DRILL .375)

G97M13S500T3636

G99G0X0Y0

Z.1

G83Z-.865Q.075F.0035

G0G80Z.1

M5

G28W0

M1

N35(DRILL .323)

G97M13S400T3535

S4=400M113

G99G0X0Y0

Z-.65

G83Z-1.0Q.035F.0025

G0G80Z.1

M5

M115

G28W0

M1

N37(BB R.008 ROUGH)

G97M13S1696T3737

G99G0X.33Y0

Z.1

G1Z.0026F.005

Z-.9595

X.31

G0Z.0026

G1X.33

X.35

Z-.7672

X.3362Z-.7741

G2X.33Z-.7815R.0105  
G0Z.0026  
G1X.35  
X.37  
Z-.7572  
X.35Z-.7672  
G0Z.0026  
G1X.37  
X.39  
Z-.0575  
X.3816Z-.0647  
G2X.3788Z-.07R.0105  
G1Z-.7528  
X.37Z-.7572  
G0Z.0026  
G1X.39  
X.41  
Z-.0402  
X.39Z-.0575  
G0Z.0026  
G1X.41  
X.43  
Z-.0228  
X.41Z-.0402  
G0Z.0026  
G1X.43  
X.45  
Z-.0055  
X.43Z-.0228  
G0Z.0026  
G1X.45  
X.47  
Z.0025  
G2X.4532Z-.0027R.0105  
G1X.45Z-.0055  
G0Z.0026  
G1X.47  
X.49  
Z.0025  
X.4714  
X.47  
G0Z.0026  
G1X.49  
X.495  
Z.0025

X.49  
G0X.31  
G0Z.05  
M5  
G28W0  
M1

N301(TURN R.016)  
G97M14S1550T3131  
G99G0X.4714Y0  
Z.1  
G1Z0F.0025  
G3X.4935Z-.0046R.0156  
G1X.5542Z-.0349  
G3X.5633Z-.046R.0156  
G1Z-.837  
X.6535  
G3X.6847Z-.8526R.0156  
G1  
G0X.72  
Z0  
X.6  
G1X.3  
G0Z.1  
M5  
G28W0  
M1

N33(BB R.008 FINSH)  
G97M13S1696T3333  
G99G0X.4829Y0  
Z.1  
G1Z0F.0025  
G2X.4518Z-.009R.018  
G1X.3886Z-.0637  
G2X.3838Z-.0727R.018  
G1Z-.7538  
X.3827Z-.7543  
X.3455Z-.7729  
G2X.335Z-.7856R.018  
G1  
G0Z.25  
M5  
G28W0  
M1

N32(THREADING EXTERNAL)

G97M13S1000T3232

G99G0X0.65Y0Z.3

Z.25

G76P010060Q.0015R.001

G76X.496Z-.8R0.OP.0415Q.002F.0556

G0X.65

Z.25

M5

G28W0

M1

N38(THREADING INTERNAL)

G97M13S1000T3838

G99G0X0.32Y0Z.3

Z-.65

G76P010060Q.0015R.001

G76X.375Z-1.1R0.OP.020Q.002F.0416

G0X.32

Z.25

M5

G28W0

M1

N34(1/4 END MILL)

T3434

G0G53Z0

G97M113S4=1000

M8

M38

G0G98Y0.CO.

X1.1803

Z.1

G12.1

G1X.5281C.2633F200.

Z-1.087F6.

G41X.4281F5.

C-.4285

X-.4289

C.4285

X.4281

C.2633

G40X.5281

Z.25F200.

G13.1  
G0X1.1803  
( OPERATION 10, MILL CONTOUR )  
X1.1535Y0.CO.

G12.1  
G1X.5131C.2633F200.  
Z-1.087F6.  
G41X.4131F5.  
C-.4135  
X-.4139  
C.4135  
X.4131  
C.2633  
G40X.5131  
Z.25F200.

G13.1  
G0X1.1535  
( OPERATION 11, MILL CONTOUR )  
X1.1447Y0.CO.

G12.1  
G1X.5081C.2633F200.  
Z-1.087F6.  
G41X.4081F5.  
C-.4085  
X-.4089  
C.4085  
X.4081  
C.2633  
G40X.5081  
Z.25F200.

G13.1  
G0G53Z0  
M9  
M115  
M39(INDEXING OFF)  
M1

N90(PART EJECTION)  
T3939  
G0X0.  
Z-1.5  
M24  
M11  
G4X.5  
M31

G4X0.5

M32

G04X1.

M31

G4X1.

M18

G28W0.

M32

T3030

M24

G4U0.5

M32

G4U0.5

M25

M1

N99(PICK OFF)

T3030

G0X0.

M11

M1007

M1008

G0Z.2

G98G1Z-2.0F10.

Z-2.125F5.0

M10

G4U0.5

M1009

M1010

G1W0.04F40

M1011

G28W0.

M1012

M1

M30

%

**END OF PROGRAM**



## **Tool Layout**

### **MAIN SPINDLE**

T0101 CUT OFF  
T0202 ROUGH TURN R.016  
T0303 FINISH TURN R.008  
T0404 OD GROOVE W.094  
T0505 EXT THREADING -20  
T1111 INSERT DRILL .435  
T1212 DRILL .325  
T1313 BB ROUGH ID R.015  
T1414 BB FINSH ID R.008  
T2222 END MILL .3125  
T2525 CARBIDE.234 DRILL  
T2323 CARBIDE DRILL .218  
T2424 MICRO DRILL .093

### **SUB SPINDLE**

T3131 ROUGH TURN  
T3232 EXTERNAL THREADING  
T3636 DRILL .375  
T3535 .328 DRILL  
T3737 BORING BAR ROUGH  
T3333 BORING BAR FINISH  
T3838 INTERNAL THREADING  
T3434 1/4 END MILL

## **How To Take Tool Offsets**

### **Overview:**

The tool change macros automatically set the tool offsets at a predetermined location for standard swiss style tooling. When installing a tool, you call the empty tool station to a known position over the material and place the tool in the tool block while letting it rest on the material. **Your offset values will be zero.**

If you have **non-standard tooling**, it may be necessary to “Measure” the tool offset.

When measuring the tool, the offsets value will be the difference between the macro position and the tool position. The main spindle reference tool is T101. The sub spindle reference tool is T3030.

Please read the tool setting procedure for both cases below.

### **MAIN SPINDLE**

#### **Setting reference tool (T101) for standard swiss style tooling**

##### **IMPORTANT!!**

**Before you set any tools, you must set T101 parting/reference tool. (Standard Metric Tooling)**

1. Make sure the tool #1 offsets in length and wear are set to zero.
2. Always start by calling up T0100 to the stock diameter in X without a tool mounted in the tool block.  
i.e. T0100 G0 X.75; for .750” (diameter stock).
3. Place the Parting tool in the tool block and drop it down on top of the .750” material.
4. Tighten the tool in place. (The X axis offset value should be zero)
5. Use the handwheel to move the material to a Z position to create a “top cut” (make a clean face on the stock material).
6. Run the first section of the program to create a clean face on the material and establish the Z1 axis zero reference.
7. Your parting tool and Z reference zero are now set. Use this material face to set the remaining tools.

**IMPORTANT NOTE:** If you unclamp the material or turn the machine off, you must repeat steps 5 thru 6 before setting other tools.

### **Setting STANDARD Turning Tools**

1. Before setting tools, make sure the parting/reference tool has been set. (Steps 5-6 of reference tool setting must be run before proceeding to the next steps)
2. Use MDI to call the empty tool position to the stock value.  
i.e. G0 T0200 X.75;
3. Place tool in tool block and drop it down to the top of the .750" diameter material.
4. Tighten tool. If this is a standard right hand turning tool, you are done.  
If the tool is not standard, see NON-STANDARD TOOL SETTING below.

### **Setting ID tools**

1. Place the ID tool in the tool station. Leave the tool loose and push the tool as far back from the spindle possible.
2. In MDI call up the tool to Z zero.  
i.e. G0 T1100 Z0. ; (The machine will move to the center of T1111 and the material will be at Z zero)
3. Move the tool against the face of the material.
4. Tighten tool.
5. If the tool is a center working tool, like drill, you are done.
6. If tool is a boring bar, find the distance from the tool tip to the center of the tool, multiply it by 2 and enter it in the X axis offset "Length" value.

### **NON-Standard Tool Setting**

If you are using a back turn (left hand) tool or a long ID tool, you will need to measure the tool offset.

### **Non-Standard Tool Offset Setting X Axis**

1. Clear offset values from the Length and Wear offset table for the desired tool.
2. In MDI, call tool to be measured  
i.e. T0200
3. In Manual Mode, use hand wheel to turn a diameter.
4. Measure the diameter i.e. .748"
5. Go the Monitor page and select "Offsets".
6. Select "Length" Offsets
7. Cursor to the desired X Length offset
8. Input ".748"
9. Press "Measure"

### **Non-Standard Tool Offset Setting Z Axis**

1. Clear offset values from the Length and Wear offset table for the desired tool.
2. In MDI, call tool to be measured  
i.e. T0200
3. In Manual Mode, use hand wheel to touch off part face using a .250" diameter pin.
4. Go the Monitor page and select "Offsets".
5. Select "Length" Offsets
6. Cursor to the desired Z Length offset
7. Input ".250"
8. Press "Measure"

### **SUB SPINDLE**

**Note: The X and Y offsets for the center of the ID tool stations are preset by the tool change macros.**

### **Setting Length Offsets for driven or fixed tooling in ID stations**

1. Clear offset values from the Length and Wear offset table for the desired tool.
2. In MDI, call tool to be measured  
i.e. T3100
3. In Manual Mode, use hand wheel to touch off part face using a .250" diameter pin.
4. Go the Monitor page and select "Offsets".
5. Select "Length" Offsets
6. Cursor to the desired Z Length offset
7. Input ".250"
7. Press "Measure" If center tool like a drill, your done.  
If the tool is a boring bar, find the distance from the tool tip to the center of the tool, multiply it by 2 and enter it in the X axis offset "Length" value.

### **Using Sub Spindle Turning Tool Stations 1-3**

1. Clear offset values from the Length and Wear offset table for the desired tool.
2. In MDI, call tool to be measured  
i.e. T0100
3. In Manual Mode, use hand wheel to turn a diameter.
4. Measure the diameter i.e. ".498"
5. Go the Monitor page and select "Offsets".
6. Select "Length" Offsets
7. Cursor to the desired X Length offset
8. Input ".498"
9. Press "Measure"

## **Notes on taking offsets:**

It is very important to call up the tool with no offset before using the “Measure” Function.