


## **Contents**

Introduction .....	1
G Code List .....	2
M Code List .....	3
Sample Part .....	5
Sample Program .....	6
Tool Layout .....	21
How To Take Tool Offsets .....	22
Notes on taking offsets: .....	25



## **Introduction**

The Purpose of this document is to give additional information for the instructional videos. Please click on the Table of Content to jump to the desired information.

## G Code List

### ■ G CODE LIST

CODE	DESCRIPTION	CODE	DESCRIPTION
G00	Positioning (Rapid traverse)		
G01	Linear interpolation (Cutting feed)	G87	S1 deeping cycle(X axis)
G02	Circular interpolation CW	G88	S1 cross tapping(X axis)
G03	Circular interpolation CCW	G90	Outer diameter/internal diameter cutting cycle
G04	Dwell	G92	Thread cutting cycle(auto)
G12.1	Polar coordinate interpolation mode	G96	Constant round speed.
G13.1	Polar coordinate interpolation cancel mode	G97	Constant speed.
G17	Xp Yp plane selection	G98	Per minute feed ( mm/min )
G18	Zp Xp plane selection	G99	Per revolution feed ( mm/rpm )
G19	Yp Zp plane selection	G320	British Imperial System (Restart machine.)
G28	Return to reference position	G321	Metric System (Restart machine.)
G30	2nd reference position return	G300	Return to programme reference point
G32	Thread cutting	G800	Main spindle angle deflection settingof C axis
G40	Tool nose radius compensation cancel	G900	Main and sub spindle angle deflection setting
G41	Tool nose radius compensation right		
G42	Tool nose radius compensation left		
G50	Coordinate system setting		
	Max. spindle speed setting		
G70	Fine cutting cycle		
G71	Horizontal cutting repeated cycle		
G72	Vertical cutting repeated cycle		
G73	Forming Processing repeated cycle		
G74	End face grooving cycle		
	End face peck drilling cycle		
G75	Side grooving cycle		
	Side peck drilling cycle		
G76	Threading Canned Cycle		
G80	Cancel machining cycle		
G83	Cycle for Z axis deep face drilling		
G84	Cycle for Z axis face tapping		

5-9

## M Code List

■ M CODE LIST FOR MAIN SYSTEM


CODE	DESCRIPTION	CODE	DESCRIPTION
M00	Programme stop	M114	Side/ Face drilling CCW
M01	Optional programme stop	M115	Side/Face drilling stop
M02	End of program	M133	Main/Sub spindle synchronous CW
M03	Spindle CW	M134	Main/Sub spindle synchronous CCW
M04	Spindle CCW	M135	Main/Sub spindle synchronous stop
M05	Spindle stop	M142	Main/Sub Z axis synchronous running
M06	Spindle position start	M143	Main/Sub Z axis synchronous running cancel
M07	Spindle position cancel	M144	Main/Sub C axis synchronous running
M08	Coolant oil start	M145	Main/Sub C axis synchronous running cancel
M09	Coolant oil cancel	M191	Sub program for top cutting by new bar ( non guide bush mode )
M10	Spindle chuck close	M192	Sub program for top cutting by new bar ( guide bush mode )
M11	Spindle chuck open	M211	Start the first backup M code
M13	Spindle CW+ coolant oil	M212	cancel the first backup M code
M14	Spindle CCW+ coolant oil cancel	M213	Start the second backup M code
M30	End of program	M214	Cancel the second backup M code
M32	Cut off detection	M215	Start the third backup M code
M34	Threading 45° back-off	M216	Cancel the third backup M code
M35	Threading 90° back-off	M217	Start the forth backup M code
M38	C axis mode enable	M218	Cancel the forth backup M code
M39	C axis mode unale	M219	Start the fifth backup M code
M43	Cut-off tool turning head of bar automatically	M220	Cancel the fifth backup M code
M60	Bar feeder pressure off	M500	Spindle load detector
M61	Bar feeder pressure on	M660	
M62	bar feeder backward by bar change	M1000	Main/Sub system Waiting command
		M1100	
M63	Confirm bar change finished		
M94	Single block bypass mode OFF		
M95	Single block bypass mode ON		
M98	Call sub programmeme		
M99	Programmeme cycle/sub programmeme finish		
M100	Spindle position (M100 C___;)		
M110	Sub spindle chuck close		
M111	Sub spindle chuck open		
M113	Side/Face drilling CW		



■ M CODE LIST FOR SUB SPINDLE

CODE	DESCRIPTION	CODE	DESCRIPTION
M00	Programme stop	M211	Start the first backup M code(W/ \$1share)
M01	Optional programme stop	M212	Cancel the first backup M code (W/ \$1share)
M02	End of programme	M213	Start the second backup M code(W/ \$1share)
M03	Spindle CW	M214	Cancel the second backup M code (W/ \$1share)
M04	Spindle CCW	M215	Start the third backup M code(W/ \$1share)
M05	Spindle stop	M216	Cancel the third backup M code (W/ \$1share)
M06	Spindle position	M217	Start the forth backup M code(W/ \$1share)
M07	Spindle position cancel	M218	Cancel the forth backup M code (W/ \$1share)
M08	Coolant oil	M219	Start the fifth backup M codes(W/ \$1share)
M09	Coolant oil cancel	M220	Cancel the fifth backup M code (W/ \$1share)
M10	Spindle chuck close	M231	Start inner coolant oil for sub spindle
M11	Spindle chuck open	M232	Stop inner coolant oil for sub spindle
M13	Spindle CW+ coolant oil	M500   M660	Spindle load detector
M14	Spindle CCW+ coolant oil cancel		
M18	Parts conveyor active	M1000   M1100	Main/Sub system Waiting command
M24	Sub Spindle air blow on		
M25	Sub Spindle air blow off		
M30	End of programme		
M31	Pusher forward (Cylinder pusher)		
M32	Pusher backward (Pnumatic cylinder pusher)		
M33	Pnumatic cylinder pusher Enjecting parts detection		
M34	Threading 45° back-off		
M35	Threading 90° back-off		
M38	C axis mode enable		
M39	C axis mode unale		
M98	Call sub programmeme		
M99	Programmeme cycle/sub programmeme finish		
M100	Spindle position (M100 C ___;)		
M113	Face drilling CW		
M114	Face drilling CCW		
M115	Face drilling stop		

**Sample Part**



## **Sample Program**

\$1

(IMTS 2018 SL42Y2)  
(MAIN SPINDLE)

M43S1500F0.0035

M11

G4X1.0

G300X-0.04Z3.275T0101

G50Z0.

M10

G4X1.0

G0X1.6Z-0.65

M1000(WAIT CODE)

M1

N6(TURNING TOOL DEG R.015 ROUGH)

G97M03S1800T0606

G99G0X1.65Z-.0025

G1X1.62F0.0035

G0X1.625Z-.1

G71U.049R.02

G71P10Q20U.005W.0025F.0135

N10G1X.4427F.0025

Z0

X.5118Z.0345

X.54Z.5412

Z.6

X.7229

X.866Z.6192

Z1.1155

X1.25

Z1.6155

X1.61

G1Z1.990

N20X1.625

G0Z-.05

G0X1.7

M1

pg. 6

818 349-9166

[www.expandmachinery.com/training](http://www.expandmachinery.com/training)

N3(TURNING TOOL R.015)

G97M03S2200T0303

G99G0X.9Z-.05

Z.599

G1X.545F.005

Z.597

G0X1.3

Z1.1145

G1X.876

Z1.1135

G0X1.7

Z1.6145

G1X1.255

Z1.6135

G0X1.65

Z-.05

X.4427

G1Z0F.0045

X.5118Z.0345

X.54Z.5412

Z.6

X.7229

X.825Z.6137

G2X.866Z.6404R.0276

G1Z1.1155

X1.1587

G2X1.25Z1.1612R.0456

G1Z1.6155

X1.5188

G2X1.61Z1.6612R.0456

G1Z1.999

G0X1.65

Z0

X.625

G1X-.035

G0Z-.05

X1.6

M1

N5(NPT THREADING)

G97M03S1800T0505

G99G0X.75Z-.15

G76P010060Q.01R.001

G76X.4884Z.5R-.0187P.0445Q.020F.055556

G0X1.00  
Z-.05  
G0X1.6  
M1

N11(5/16 SPOT DRILL)  
G97M03S1100T1111  
G99G0X0Z-0.1  
G83Z.15Q0.1F0.0035  
G80  
G0Z-.5  
M1

N12(.250 DRILL )  
G97M03S1300T1212  
G99G0X0Z-0.1  
G83Z1.35Q0.15F0.0045  
G80  
G0Z-.5  
M05  
M1

N21(1/2" 4FLT STUB E/MILL)  
M38  
T2121  
M113S3=1400  
G0G98X1.65Y1.7378Z-.1C0.  
Z.6555  
G1X.75F150.  
G42Z.6055F15.  
X.7501Y-.463  
X.75Z.8655  
Y1.6636  
G40Z.8155

G0Y1.7378Z.6555C-60.

G1X.75F150.  
G42Z.6055F15.  
X.7501Y-.463  
X.75Z.8655  
Y1.6636  
G40Z.8155

G0Y1.7378Z.6555C-120.



G1X.75F150.  
G42Z.6055F15.  
X.7501Y-.463  
X.75Z.8655  
Y1.6636  
G40Z.8155

G0Y1.7378Z.6555C-180.

G1X.75F150.  
G42Z.6055F15.  
X.7501Y-.463  
X.75Z.8655  
Y1.6636  
G40Z.8155

G0Y1.7378Z.6555C-240.

G1X.75F150.  
G42Z.6055F15.  
X.7501Y-.463  
X.75Z.8655  
Y1.6636  
G40Z.8155

G0Y1.7378Z.6555C-300.

G1X.75F150.  
G42Z.6055F15.  
X.7501Y-.463  
X.75Z.8655  
Y1.6636  
G40Z.8155

G0X1.  
X1.65  
M115  
Z-.1  
M39  
M1

N23(ENGRAVING)  
M38  
T2323  
M113S3=4000

G0G98X1.65Y0.Z-.16C-360.495  
Z1.4086  
X1.5  
G1X1.24F15.  
X1.2399Z1.3743C-360.969F387.5446  
C-374.52F916.7325  
X1.2397Z1.3964C-374.662F64.8534  
X1.2394Z1.4185C-374.519F65.2814  
X1.239Z1.4401C-374.1F189.8341  
X1.2387Z1.461C-373.412F310.7157  
X1.2386Z1.4807C-372.468F424.907  
X1.2385Z1.4982C-371.328F530.9477  
Z1.5135C-370.016F626.5998  
Z1.5265C-368.557F709.5595  
X1.2386Z1.5372C-366.975F778.641  
X1.2388Z1.5456C-365.294F833.5225  
X1.2389Z1.5516C-363.538F874.3736  
X1.2391Z1.5553C-361.731F901.4963  
X1.2392Z1.5565C-359.897F915.0556  
X1.2394Z1.5552C-358.061F914.9292  
X1.2396Z1.5515C-356.246F900.6809  
X1.2397Z1.5452C-354.476F871.6659  
X1.2398Z1.5363C-352.777F827.2726  
X1.2399Z1.5249C-351.171F767.2864  
Z1.5108C-349.684F692.3092  
Z1.494C-348.338F604.0929  
X1.2398Z1.4688C-346.867F492.2392  
X1.2397Z1.4429C-345.891F348.3473  
Z1.4167C-345.379F191.6384  
Z1.3907C-345.297F32.78  
X1.2396Z1.3653C-345.615F124.3642  
Z1.341C-346.299F268.9983  
X1.2397Z1.3182C-347.318F401.0949  
Z1.2973C-348.638F520.1149  
Z1.2787C-350.228F626.3144  
Z1.263C-352.056F719.5908  
X1.2398Z1.2505C-354.088F798.6973  
Z1.2417C-356.294F860.8156  
Z1.237C-358.64F901.6991  
Z1.2368C-361.094F916.7206  
X1.2399Z1.2417C-363.625F902.8534  
Z1.252C-366.199F860.7487  
Z1.2973C-364.262F387.5339  
Z1.2907C-362.644F859.2973  
X1.2398Z1.2874C-361.036F900.6146

Z1.2871C-359.458F916.5539  
Z1.2895C-357.933F907.1892  
Z1.2944C-356.479F875.1545  
X1.2397Z1.3017C-355.117F824.0625  
Z1.311C-353.868F757.1475  
Z1.3221C-352.753F676.5612  
Z1.3348C-351.792F583.2641  
Z1.3489C-351.005F477.3067  
Z1.3641C-350.414F358.3763  
Z1.3802C-350.038F226.5879  
Z1.3969C-349.898F83.6389  
Z1.4141C-350.015F68.7675  
X1.2398Z1.4314C-350.41F220.7915  
X1.2399Z1.4488C-351.102F366.6491  
Z1.4643C-352.018F496.5389  
X1.24Z1.4773C-353.096F614.3999  
Z1.4878C-354.307F716.2456  
X1.2401Z1.496C-355.625F797.8371  
Z1.5017C-357.022F857.6155  
Z1.5052C-358.471F896.0415  
Z1.5063C-359.946F914.5186  
X1.24Z1.5051C-361.419F914.4446  
Z1.5018C-362.862F896.624  
Z1.4963C-364.249F861.0472  
Z1.4886C-365.553F806.9883  
X1.2399Z1.4788C-366.746F733.4202  
Z1.467C-367.801F639.764  
Z1.4532C-368.691F526.8931  
Z1.4374C-369.389F398.0505  
Z1.4197C-369.868F259.0969  
X1.2401C-367.159F916.7234  
X1.2406C-364.449F916.7071  
X1.2407C-361.74F916.7314  
X1.2399C-359.031F916.6501  
X1.24Z1.4086C-359.505F387.4931  
GOX1.65  
Z-.1  
M115  
M39  
G18  
M1  
  
N99(CUT OFF W.118)  
T0101  
G99GOX1.7Z1.995

M1007(WAIT CODE)  
M133S50R0  
M1008(WAIT CODE)  
M1009(WAIT CODE)  
M39  
M1010  
S1300  
(M8)  
M1011  
M1012  
G1X-.02F0.0032  
M1013(WAIT CODE)  
M1014(WAIT CODE)  
M135  
M5  
(\*\*\*Remove parenthesis for Bar Feed\*\*\*)  
(M95)  
G4U0.1  
(/M192S1600F0.0016)  
G4U0.1  
(M94)  
M1015  
M30

\$2

(SUB SPINDLE IMTS)  
M5  
G28W0  
M1000  
N1  
T0101  
G99G97G80G40G18G0  
G97S2=2300M4  
G0X1.65Y0  
Z.01  
G1G99X.375F.005  
G0Z.1  
X1.65  
Z-.05  
G1X1.625F.0025  
Z-.0256  
G2X1.5737Z0.R.0256  
G1X.375

G0Z2.5  
M05  
M1

N36(FACE GROOVING)

M05  
G4X.5  
G97M03S1300T3636  
G99G0X1.555Y0

Z.1

G1Z.0025F.002

G0Z.05

X1.52

G1Z-.01

Z-.005

Z-.02

Z-.005

Z-.03

Z-.025

Z-.04

Z-.035

Z-.05

Z-.045

Z-.06

Z-.055

Z-.067

G0Z.05

X1.518

G1Z-.01

Z-.005

Z-.02

Z-.005

Z-.03

Z-.025

Z-.04

Z-.035

Z-.05

Z-.045

Z-.06

Z-.055

Z-.065

Z-.06

Z-.069

G0Z.05

X1.518

G1Z-.0708  
G0Z.05

X1.561  
G1Z0.F.001  
G2X1.525Z-.018R.018  
G1Z-.068  
G3X1.511Z-.075R.007  
G0Z.05

X1.475  
G1Z0.  
G3X1.511Z-.018R.018  
G1Z-.068  
G2X1.518Z-.074R.007  
X1.525Z-.068R.007  
G1Z-.018  
G3X1.561Z0.R.018  
G0Z.1  
G0Z2.5M5  
M1

N38(.250 DRILL )  
G97M03S1500T3838  
G99G0X0Z.1  
G83Z-.75Q0.1F0.0045  
G80  
G0Z2.5  
M05  
M1

N37(BORING BAR)  
G97M03S1900T3737  
G99G0X.27Z.1  
G1Z.0026F.0095  
Z-.1475  
X.266  
G2X.25Z-.1512R.0105  
G0Z.0026  
G1X.27  
X.29  
Z-.1475  
X.27  
G0Z.0026  
G1X.29

X.31  
Z-.1475  
X.29  
G0Z.0026  
G1X.31  
X.33  
Z-.1475  
X.31  
G0Z.0026  
G1X.33  
X.35  
Z-.1475  
X.33  
G0Z.0026  
G1X.35  
X.37  
Z-.1475  
X.35  
G0Z.0026  
G1X.37  
X.39  
Z.0025  
G2X.37Z-.008R.0105  
G0Z.0026  
G1X.39  
X.41  
Z.0025  
X.391  
X.39  
G0Z.0026  
G1X.41  
X.43  
Z.0025  
X.41  
G0Z.0026  
G1X.43  
X.4357  
Z.0025  
X.43  
G0X.25  
Z.05  
X.411  
G1Z0.F.0035  
G2X.375Z-.018R.018  
G1Z-.15

X.266  
G2X.25Z-.158R.008  
G1  
G0Z2.5  
M05  
M1  
  
N32(END MILL .125)  
M38  
M113S4=4000  
T3232  
G17  
G0C0.  
G0G98X.7578Y.1447C0.  
Z.1  
G1Z-.05F2.  
X.7018Y.1314F6.0  
X.6629Y.1223  
X.6982Y-.0276  
G3X.9171Y.0631R.06  
G1X.5933Y.5868  
G3X.5568Y.5717R.01  
G1X.6629Y.1223  
X.7018Y.1314  
G0Z.05  
X.7578Y.1447  
Z.05  
G1Z-.1F2.  
X.7018Y.1314F6.0  
X.6629Y.1223  
X.6982Y-.0276  
G3X.9171Y.0631R.06  
G1X.5933Y.5868  
G3X.5568Y.5717R.01  
G1X.6629Y.1223  
X.7018Y.1314  
G0Z.02  
X.7578Y.1447  
Z0.  
G1Z-.15F2.  
X.7018Y.1314F6.0  
X.6629Y.1223  
X.6982Y-.0276  
G3X.9171Y.0631R.06  
G1X.5933Y.5868



G3X.5568Y.5717R.01  
G1X.6629Y.1223  
X.7018Y.1314  
G0Z.01  
( OPERATION 10, MILL ROUGHING )  
( BACK SIDE )  
( TOOL POSITION 1, .125 DIA. FINISH ENDMILL )  
G0G98X-.7531Y.1427  
G1Z-.05F2.  
X-.8021Y.173F6.0  
X-.8361Y.194  
X-.9171Y.0631  
G3X-.6982Y-.0276R.06  
G1X-.5568Y.5717  
G3X-.5933Y.5868R.01  
G1X-.8361Y.194  
X-.8021Y.173  
G0Z.02  
X-.7531Y.1427  
Z.02  
G1Z-.1F2.  
X-.8021Y.173F6.0  
X-.8361Y.194  
X-.9171Y.0631  
G3X-.6982Y-.0276R.06  
G1X-.5568Y.5717  
G3X-.5933Y.5868R.01  
G1X-.8361Y.194  
X-.8021Y.173  
G0Z.02  
X-.7531Y.1427  
Z0.  
G1Z-.15F2.  
X-.8021Y.173F6.0  
X-.8361Y.194  
X-.9171Y.0631  
G3X-.6982Y-.0276R.06  
G1X-.5568Y.5717  
G3X-.5933Y.5868R.01  
G1X-.8361Y.194  
X-.8021Y.173  
G0Z.02  
( OPERATION 12, MILL CONTOUR )  
( BACK SIDE )  
( TOOL POSITION 1, .125 DIA. FINISH ENDMILL )

X.8542Y.0982  
G1Z-.14F15.  
Z-.15F1.5  
X.8883Y.1192F8.5  
X.9213Y.0657  
G2X.6933Y-.0287R.0625  
G1X.552Y.5706  
G2X.5976Y.5894R.0125  
G1X.8883Y.1192  
X.8542Y.0982  
G0Z.02  
( OPERATION 13, MILL CONTOUR )  
( BACK SIDE )  
( TOOL POSITION 1, .125 DIA. FINISH ENDMILL )  
X-.7167Y.0465  
G1Z-.14F15.  
Z-.15F1.5  
X-.6778Y.0373F8.5  
X-.6933Y-.0287  
G2X-.9213Y.0657R.0625  
G1X-.5976Y.5894  
G2X-.552Y.5706R.0125  
G1X-.6778Y.0373  
X-.7167Y.0465  
G0Z.1  
G28W0  
M39  
M05  
M115  
G18  
M1  
  
N33(CHAMFER MILL 6MM)  
M38  
M113S4=2600  
T3333  
G17  
G0C0.  
G0G98X.9267Y.1806C0.  
Z.1  
G1Z-.03F25.  
X.9522Y.1964F16.  
X1.0021Y.1157  
G2X.6009Y-.0505R.11  
G1X.4595Y.5487

G2X.6784Y.6394R.06  
G1X.9522Y.1964  
X.9267Y.1806  
G0Z.1

X-.5938Y.11  
G1Z-.03F25.  
X-.5646Y.1031F16.  
X-.6009Y-.0505  
G2X-1.0021Y.1157R.11  
G1X-.6784Y.6394  
G2X-.4595Y.5487R.06  
G1X-.5646Y.1038Y.11  
G0Z.1  
G28W0  
M39  
M05  
M115  
G18  
M1

N39(PART EJECTION)  
G0G53Z0  
T3939  
G0X0.  
Z0  
M24  
M11  
G4X.5  
M31  
G4X0.5  
M32  
G04X1.  
M18  
G4U0.5  
M25  
G0G28W0  
M1

N99(PICK OFF)  
T3030  
M11  
G4X.2  
M1007  
M1008



**Instructional Video Series  
GenTurn SL42Y2  
Video Support Document**

G0Z2.0M24  
G98G1Z0F100.  
M1009  
M25  
M1010  
M1011  
M10  
G4U.5  
M1012  
M1013  
G1W0.04F40  
M1014  
G28W0.  
M1015  
M30  
%

**END OF PROGRAM**



## **How To Take Tool Offsets**

### **Overview:**

The tool change macros automatically set the tool offsets at a predetermined location for standard swiss style tooling. When installing a tool, you call the empty tool station to a known position over the material and place the tool in the tool block while letting it rest on the material. **Your offset values will be zero.**

If you have **non-standard tooling**, it may be necessary to “Measure” the tool offset.

When measuring the tool, the offsets value will be the difference between the macro position and the tool position. The main spindle reference tool is T101. The sub spindle reference tool is T3030.

Please read the tool setting procedure for both cases below.

### **MAIN SPINDLE**

#### **Setting reference tool (T101) for standard swiss style tooling**

##### ***IMPORTANT!!***

***Before you set any tools, you must set T101 parting/reference tool. (Standard Metric Tooling)***

1. Make sure the tool #1 offsets in length and wear are set to zero.
2. Always start by calling up T0100 to the stock diameter in X without a tool mounted in the tool block.  
i.e. T0100 G0 X.75; for .750” (diameter stock).
3. Place the Parting tool in the tool block and drop it down on top of the .750” material.
4. Tighten the tool in place. (The X axis offset value should be zero)
5. Use the handwheel to move the material to a Z position to create a “top cut” (make a clean face on the stock material).
6. Run the first section of the program to create a clean face on the material and establish the Z1 axis zero reference.
7. Your parting tool and Z reference zero are now set. Use this material face to set the remaining tools.

**IMPORTANT NOTE:** If you unclamp the material or turn the machine off, you must repeat steps 5 thru 6 before setting other tools.

### Setting STANDARD Turning Tools

1. Before setting tools, make sure the parting/reference tool has been set. (Steps 5-6 of reference tool setting must be run before proceeding to the next steps)
2. Use MDI to call the empty tool position to the stock value.  
i.e. G0 T0200 X.75;
3. Place tool in tool block and drop it down to the top of the .750" diameter material.
4. Tighten tool. If this is a standard right hand turning tool, you are done.  
If the tool is not standard, see NON-STANDARD TOOL SETTING below.

### Setting ID tools

1. Place the ID tool in the tool station. Leave the tool loose and push the tool as far back from the spindle possible.
2. In MDI call up the tool to Z zero.  
i.e. G0 T1100 Z0. ; (The machine will move to the center of T1111 and the material will be at Z zero)
3. Move the tool against the face of the material.
4. Tighten tool.
5. If the tool is a center working tool, like drill, you are done.
6. If tool is a boring bar, find the distance from the tool tip to the center of the tool, multiply it by 2 and enter it in the X axis offset "Length" value.

### NON-Standard Tool Setting

If you are using a back turn (left hand) tool or a long ID tool, you will need to measure the tool offset.

### Non-Standard Tool Offset Setting X Axis

1. Clear offset values from the Length and Wear offset table for the desired tool.
2. In MDI, call tool to be measured  
i.e. T0200
3. In Manual Mode, use hand wheel to turn a diameter.
4. Measure the diameter i.e. .748"
5. Go the Monitor page and select "Offsets".
6. Select "Length" Offsets
7. Cursor to the desired X Length offset
8. Input ".748"
9. Press "Measure"

### **Non-Standard Tool Offset Setting Z Axis**

1. Clear offset values from the Length and Wear offset table for the desired tool.
2. In MDI, call tool to be measured  
i.e. T0200
3. In Manual Mode, use hand wheel to touch off part face using a .250" diameter pin.
4. Go the Monitor page and select "Offsets".
5. Select "Length" Offsets
6. Cursor to the desired Z Length offset
7. Input ".250"
8. Press "Measure"

### **SUB SPINDLE**

***Note: The X and Y offsets for the center of the ID tool stations are preset by the tool change macros.***

#### **Setting Length Offsets for driven or fixed tooling in ID stations**

1. Clear offset values from the Length and Wear offset table for the desired tool.
2. In MDI, call tool to be measured  
i.e. T3100
3. In Manual Mode, use hand wheel to touch off part face using a .250" diameter pin.
4. Go the Monitor page and select "Offsets".
5. Select "Length" Offsets
6. Cursor to the desired Z Length offset
7. Input ".250"
7. Press "Measure" If center tool like a drill, your done.  
If the tool is a boring bar, find the distance from the tool tip to the center of the tool, multiply it by 2 and enter it in the X axis offset "Length" value.

#### **Using Sub Spindle Turning Tool Stations 1-3**

1. Clear offset values from the Length and Wear offset table for the desired tool.
2. In MDI, call tool to be measured  
i.e. T0100
3. In Manual Mode, use hand wheel to turn a diameter.
4. Measure the diameter i.e. ".498"
5. Go the Monitor page and select "Offsets".
6. Select "Length" Offsets
7. Cursor to the desired X Length offset
8. Input ".498"
9. Press "Measure"



## **Notes on taking offsets:**

It is very important to call up the tool with no offset before using the “Measure” Function.